

Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Job Number:	86981	Da	te of Repo	ort:	11/23/2015
Model Number	SBE 37SM	Se	rial Numb	er:	37SM25541-1853
the calibration iden	tifies a problem, then	ated 'as received', without adj a second calibration is perfor is damaged or non-functiona	rmed after w	ork is comple	eted. The 'as received'
must choose whethe during deployment.	er the 'as received' cal In SEASOFT enter t	provided, listing coefficients to ibration or the previous calib he chosen coefficients. The ASOFT manual). Calibratio	bration better coefficient 'd	r represents t offset' allows	he sensor condition a small correction for
					_
'AS RECEIVED C	CALIBRATION'		✓ Per	formed	☐ Not Performed
·	=	Drift since		+0.0001	
'AS RECEIVED C Date: 11/21/2015 Comments:	=	Drift since			
Date: 11/21/2015 Comments:	5	Drift since	last cal:	+0.0001	0 Degrees Celsius/year
Date: 11/21/2015	5	Drift since	last cal:		
Date: 11/21/2015 Comments:	5	Drift since	last cal: [+0.0001	0 Degrees Celsius/year