## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 7021 CALIBRATION DATE: 25-Nov-15

SBE 16plus V2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = 1.243574e-003 a1 = 2.778170e-004 a2 = -1.552670e-006 a3 = 1.993162e-007

BATH TEMP (° C)	INSTRUMENT OUTPUT (counts)	INST TEMP (° C)	RESIDUAL (° C)
1.0000	564066.200	1.0000	-0.0000
4.5000	498093.900	4.5001	0.0001
15.0000	336795.900	15.0001	0.0001
18.5000	294086.600	18.4998	-0.0002
24.0000	236507.100	24.0001	0.0001
29.0000	193001.900	29.0001	0.0001
32.5000	166860.500	32.4999	-0.0001

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e+009 + 1.024e+008) / (2.048e+004 - MV \* 2.0e+005)

Temperature ITS-90 (°C) =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

