

Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	83585	Date of	Report	:	3/9/2015
Model Number	SBE 37SM	Serial I	Number	: 3	37SM36048-3767
the calibration iden	tifies a problem, then o	ted 'as received', without adjustmo a second calibration is performed o is damaged or non-functional, or l	ıfter work	is complete	ů ů
must choose whethe during deployment. drift between calibro subsequent data.	er the 'as received' cali In SEASOFT enter that ations (consult the SE	rovided, listing coefficients to conbration or the previous calibration he chosen coefficients. The coefficients and coefficients. Calibration coefficients are manual.	n better re cient 'offs ficients o	presents the et' allows	ne sensor condition a small correction for
'AS RECEIVED C	ALIDKATION	V	_ 1 (110)		
Date: 3/7/2015	ALIBRATION			-0.00004	
0/7/00/5		Drift since last of			
Date: 3/7/2015				-0.00004	Degrees Celsius/year Not Performed
Date: 3/7/2015 Comments:			Perfo	-0.00004	Degrees Celsius/year