Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 4139 CALIBRATION DATE: 02-Apr-24 SBE 16plus TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

a0 = 1.280654e-003 a1 = 2.541218e-004 a2 = 7.619189e-007 a3 = 1.220921e-007

| BATH TEMP | INSTRUMENT | INST TEMP | RESIDUAL |
|-----------|-----------------|-----------|----------|
| (° C) | OUTPUT (counts) | (° C) | (° C) |
| 1.0000 | 632674.800 | 1.0000 | -0.0000 |
| 4.5000 | 562067.400 | 4.5001 | 0.0001 |
| 15.0000 | 386459.273 | 14.9999 | -0.0001 |
| 18.5000 | 339228.000 | 18.5000 | 0.0000 |
| 24.0000 | 275071.800 | 23.9998 | -0.0002 |
| 29.0000 | 226208.200 | 29.0003 | 0.0003 |
| 32.5000 | 196695.273 | 32.4999 | -0.0001 |

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV * 2.900e+009 + 1.024e+008) / (2.048e+004 - MV * 2.0e+005)

Temperature ITS-90 (°C) = $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

