Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

## SENSOR SERIAL NUMBER: 0521 CALIBRATION DATE: 02-Aug-17

## SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.24338238e-003 h = 6.10108047e-004 i = 7.20840890e-006j = -1.11531920e-006

f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
1.0000	2690.702	0.9999	-0.00012
4.5000	2908.146	4.5002	0.00022
15.0000	3634.749	14.9999	-0.00013
18.4999	3902.895	18.4998	-0.00008
23.9999	4351.766	23.9999	0.00002
28.9999	4789.953	29.0002	0.00028
32.5000	5114.226	32.4998	-0.00019

f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( ${}^{\circ}C$ ) = instrument temperature - bath temperature

