Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	Date of Rep	ort:		12/1/2015	
Model Number	SBE 16Plus	Serial Num	ber:	161	P29504-4285	
the calibration iden	tifies a problem, then	nted 'as received', without adjustments, a a second calibration is performed after w is damaged or non-functional, or by cus	vork is com	pleted.		
must choose whethe during deployment.	er the 'as received' cal In SEASOFT enter t ations (consult the SE	provided, listing coefficients to convert se ibration or the previous calibration bette he chosen coefficients. The coefficient ASOFT manual). Calibration coefficient	er represent 'offset' allo	s the se ws a sn	ensor condition nall correction for	
Date: 11/26/2015		Drift since last cal:	-0.000	38	Degrees Celsius/year	
Comments:	_				1 ,	
CALIBRATION AFTER REPAIR'		□ Pe	☐ Performed ✓ Not Performed			
Date:	7	Drift since Last cal:			Degrees Celsius/year	
		Difft since Last car.			1 Degrees Constant your	
Comments:	_	Difft since Last car.			_ Bogicos constastycan	