5/14/2018 Form Input Data

Records for Mooring: 18MTITAEPR-1A

alternate name:

<u>Deployment</u> <u>Recovery</u>

Cruise Number: **DY1805** Cruise Number: **DY1809**

Deployment Date/Time (GMT): Recovery Date/Time (GMT):

2018-05-05 02:10:00

GPS latitude: 60 01.70 N GPS latitude:

GPS longitude: 172 47.33 W GPS longitude:

CTD cast no: CTD041 CTD cast no:

Actual Deployment Depth (m): 65

Timekeeper: Bridge Timekeeper: Bridge

Chief Scientist: Proctor Chief Scientist: Lebon

Pre-Deployment - Mooring Diagram

Estimated latitude (N): 60 01.81

Estimated longitude (W): 172 47.60

Estimated Deployment depth: 72

Estimated Recovery Date: 2018-10-01

5/14/2018 Form Input Data

Records for Mooring: 18MTITAEPR-1A

Comments:

Short all Eco-Fluorometers Remove all Eco-Fluorometer caps Plug in SBE-16 pumps Remove optode caps rumor is that the prawler from 18bsitaepr2a and this prawler got swapped (does that include the line or just the sensor?) no reference in ship notes

Deployed Instruments: 18MTITAEPR-1A

Est. Depth	Actual Depth	Instrument	Serial No.	Instrument notes	Performance Notes	Prepped	Dep.	Rec.	Data Statu
-1	-1	Wind		Need to get S/N later		У	У		
-1	-1	<u>Compass</u>	22028930	SMR3400		У	У		
-1	-1	<u>ATRH</u>	314012044			У	У		
-1	-1	<u>Barometer</u>	1685193			У	У		
0	0	<u>Buoy</u>	BERO			У	У		
О	0	SBE-16	7021	Plug in Pump		У	У		
O	0	<u>Optode</u>	<u>524</u>	On Seacat		У	У		
0	0	Eco- Fluorometer FLSB	1838	Li Batts		У	У		
0	0	<u>SBE-56</u>	<u>2452</u>	Li Batts		У	У		
0.9	1	<u>Prawler</u>	9	Li Batts		У	У		
1	1	<u>Optode</u>	2817	On Prawler		У	У		
1	1	CTD	709-0026	On Prawler		У	У		
1	o	Eco- Fluorometer FLNTUS	1075	On Prawler, FLNTUS		У	У		

5/14/2018 Form Input Data

52	0	MTR	<u>4110</u>	did not	У	n	
				fit in cage			
52	0	MTR	<u>3200</u>		У	У	
57	0	MTR	4120		У	У	
57	0	MTR	4121		У	У	
62	0	MTR	4041		У	У	
62	0	MTR	<u>4070</u>		У	У	
63	0	8242AA Release	<u>51694</u>		У	У	

Does the release have new batteries?: Yes No
If not new, how many months were batteries used? 0 month

Strausz

PMEL EcoFOCI