Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0710 CALIBRATION DATE: 07-Mar-15

SBE 3 TEMPERATURE CALIBRATION DATA

ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS:

g = 4.79526915e-003 h = 6.77434351e-004 i = 2.94971677e-005j = 2.69624888e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT FREQ	INST TEMP	RESIDUAL
(ITS-90)	(Hz)	(ITS-90)	(ITS-90)
-1.5000	5797.393	-1.5000	0.00000
0.9999	6132.204	1.0000	0.00008
4.5000	6624.090	4.4999	-0.00008
8.0000	7143.665	7.9999	-0.00014
11.4999	7691.661	11.4999	0.00000
14.9999	8268.768	15.0000	0.00009
18.4999	8875.646	18.5001	0.00018
21.9999	9512.907	22.0000	0.00010
25.4999	10181.150	25.4997	-0.00018
29.0000	10881.054	28.9997	-0.00027
32.5000	11613.220	32.5002	0.00021

Temperature ITS-90 = $1/\{g + h[ln(f_0/f)] + i[ln^2(f_0/f)] + j[ln^3(f_0/f)]\}$ - 273.15 (°C) Residual = instrument temperature - bath temperature

