SAT-QR-99016 (v 1.1.0)	SATLANTIC
Verification Checklist PAR	
Serial Number: 1085 TDP: 2.1.0 Project Number: 2016-7069 Model:	Firmware: 2.30 Shallow (PAR 1000m)
Options:	Deep (PAR 7000m) Serial Log Linear Company Com
Accessories:	In-Air IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
Shallow Deep AUV	RS-232 and Analog Cable
Calibration Saturation: 7300. 4 µmol photons•m-2•s-1	Date: 10 / 11 / 120 10
Pressure Test Pressure test not required if	Rated to:meters
Performance Active current (at 12 Vdc) 19 m/ (s 25 mA) No pin-to-pin shorts F Ground fault free	
Reality Check Agreement: 2.30%(< 5%)	Date: 10 111 1 2016
Configuration Calibration coefficients stored (Serial only) Analog Out: OK N/A Standard settings configuration Custom configuration N/A	
Accessories Check Cables: O	K T NAP
Finishing Optical surfaces clear SIP file tested with SatView	w F N/A F
This final inspection and verification of the PAR sensor is performed after all other work is complete. The inspection is conducted and QA countersigned by qualified Satlantic technicians.	
Quality Assurance:	Date: 2010 1 11 1 10