Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Job Number:	77407	Date of Rep	ort:	2/7/2014
Model Number	SBE 37SM	Serial Num	ber:	37SM28082-2341
If the calibration id calibration is not pe	entifies a problem, the erformed if the sensor	ated 'as received', without adjustments, a en a second calibration is performed afte is damaged or non-functional, or by cust	r work is com tomer request	pleted. The 'as received'
must choose whethe during deployment.	er the 'as received' cali In SEASOFT enter to ations (consult the SE	provided, listing coefficients to convert se ibration or the previous calibration bette he chosen coefficients. The coefficient (ASOFT manual). Calibration coefficient	er represents t 'offset' allows	he sensor condition a small correction for
Date: 2/6/2014]	Drift since last cal:	+0.0002	5 Degrees Celsius/year
Comments:	_			
'CALIBRATION A Date: Comments:	AFTER REPAIR'	☐ Pe Drift since Last cal:	rformed	✓ Not Performed Degrees Celsius/year