

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

## **Temperature Calibration Report**

Pacific Marine Environmental Lab

Job Number:	62473	Date of R	Report:		1/21/2011	
Model Number	SBE 37SM	Serial Nu	ımber:	37S	M28082-2341	
If the calibration id calibration is not possible to the calibration is not possible to the calibration of the calibration is not possible to the calibration of the calibration is not possible to the calibration of the calibration is not possible to the calibration of the calibration is not possible to the calibration is not possible to the calibration of the calibration	lentifies a problem, the erformed if the sensor libration certificate is p er the 'as received' cali In SEASOFT enter to ection for drift between air apply only to subse	_	ofter work customer r t sensor fr petter repre gram SEA	is completed request. requency to a resents the se CON. The Calibration	d. The 'as received' temperature. Users ensor condition coefficient 'offset'	
Date: 1/21/2011		Drift since last cal	l: +0	.00004	Degrees Celsius/ye	ear
Comments:						
'CALIBRATION Date:	AFTER REPAIR'	Drift since Last ca	Perform	ed 🔽	Not Performed Degrees Celsius/ye	