Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

## SENSOR SERIAL NUMBER: 0658 CALIBRATION DATE: 20-Jan-21

## SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

 $\begin{array}{lll} g = & 4.19202456e-003 \\ h = & 5.96167299e-004 \\ i = & 7.70003299e-006 \\ j = & -8.33087727e-007 \end{array}$ 

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
1.0000	2522.643	0.9999	-0.00009
4.5000	2731.175	4.5002	0.00019
15.0001	3430.316	14.9998	-0.00033
18.5000	3689.146	18.5002	0.00018
24.0000	4123.170	24.0002	0.00018
29.0000	4547.696	28.9998	-0.00018
32.5000	4862.456	32.5000	0.00005

## f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( ${}^{\circ}C$ ) = instrument temperature - bath temperature

