Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 3114 CALIBRATION DATE: 19-May-22 SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.21063262e-003 h = 5.89600669e-004 i = -1.59932573e-007 j = -2.68885382e-006

f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
` ,	` '	,	` '
1.0000	2608.135	0.9997	-0.00032
4.5000	2822.655	4.5006	0.00058
15.0000	3540.351	14.9994	-0.00057
18.5000	3805.690	18.5001	0.00009
23.9999	4250.257	24.0000	0.00008
28.9999	4684.883	29.0004	0.00047
32.5001	5006.889	32.4998	-0.00034

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual (${}^{\circ}C$) = instrument temperature - bath temperature

