Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 3115 CALIBRATION DATE: 18-Apr-24 SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.18030627e-003 h = 5.98282358e-004 i = 6.51290093e-006 j = -1.58343201e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
1.0000	2462.316	0.9999	-0.00011
4.5000	2664.825	4.5002	0.00018
15.0000	3343.661	15.0001	0.00006
18.5000	3594.918	18.4997	-0.00031
24.0000	4016.444	24.0000	0.00004
29.0000	4428.924	29.0004	0.00037
32.5001	4734.768	32.4999	-0.00023

f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( ${}^{\circ}C$ ) = instrument temperature - bath temperature

