Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 1815 CALIBRATION DATE: 07-Apr-23 SBE 16 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.17253991e-003 h = 5.88757041e-004 i = 2.40688583e-006 j = -1.91028116e-006

f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
1.0000	2452.649	0.9997	-0.00032
4.5000	2655.345	4.5006	0.00057
15.0000	3333.889	14.9996	-0.00039
18.5000	3584.807	18.4998	-0.00018
24.0000	4005.345	24.0002	0.00018
29.0000	4416.444	29.0005	0.00053
32.5000	4720.965	32.4996	-0.00039

f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( ${}^{\circ}C$ ) = instrument temperature - bath temperature

