Pacific Marine Environmental Lab

Customer:

Conductivity Calibration Report

<u> </u>						
Job Number:	77407		Date of Repor	rt:	2/5/20	014
Model Number	SBE 37SM		Serial Numbe	er:	37SM2554	41-1865
sensor drift. If the	calibration identifies a rk is completed. The 'd	ated 'as received', without problem or indicates ce as received' calibration is	ll cleaning is nece	essary, then	a second ca	libration is
An 'as received' calibration certificate is provided, listing the coefficients used to convert sensor frequency to conductivity. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients. The coefficient 'slope' allows small corrections for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair or cleaning apply only to subsequent data.						
'AS RECEIVED CALIBRATION'			✓ Perf	ormed	□ Not	Performed
Date: 2/5/2014		Drift sin	ce last cal:	-0.0	0030	PSU/month*
Comments:						
'CALIBRATION	AFTER CLEANING	G & REPLATINIZIN	C' Darf	ormed	✓ Not	Performed
	TER CLEANING			Office	- Not	
Date:	_	Drift sin	ce Last cal:			PSU/month*
Comments:						
*Measured at 3.0	S/m					

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.