

**Customer:** 

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

## Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	D	ate of Repo	ort:	11/20/2015
Model Number	SBE 37SM	Se	erial Numb	er:	37SM25541-1858
the calibration iden	tifies a problem, then	ated 'as received', without ac a second calibration is perfo is damaged or non-function	ormed after wo	ork is comple	ted. The 'as received'
must choose whethe during deployment. drift between calibr subsequent data.	er the 'as received' cali In SEASOFT enter t ations (consult the SE	provided, listing coefficients ibration or the previous cali he chosen coefficients. The ASOFT manual). Calibrati	ibration better e coefficient 'd on coefficient	represents the fiset' allows is obtained af	ne sensor condition a small correction for ter a repair apply only to
	'A L LKR A THAN'				Not Dorformed
	CALIBRATION'	Drift since		<b>formed</b> -0.00006	Not Performed  Degrees Celsius/year
		Drift since			
Date: 11/20/2015	5	Drift since	last cal:		
Date: 11/20/2015 Comments:	5	Drift since	e last cal:	-0.00006	Degrees Celsius/year