## **SEA-BIRD ELECTRONICS, INC.**

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 1866 CALIBRATION DATE: 21-Dec-10

SBE 37 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 4.799621e-005a1 = 2.622777e - 004a2 = -1.265293e-006a3 = 1.315743e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	650662.5	1.0000	0.0000
4.5000	557776.4	4.5000	-0.0000
15.0000	358106.5	15.0000	0.0000
18.5000	310797.0	18.5001	0.0001
23.9999	250201.0	23.9997	-0.0002
29.0000	206633.8	29.0002	0.0002
32.5000	181319.5	32.4999	-0.0001

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

