Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2324 CALIBRATION DATE: 22-Nov-15

SBE 37 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT	INSTRUMENT	RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (Hz)	COND (S/m)	(S/m)
22.0000	0.0000	0.0000	2593.70	0.00000	0.00000
1.0000	34.6838	2.96572	5108.09	2.96573	0.00002
4.5000	34.6647	3.27183	5299.41	3.27181	-0.00002
15.0000	34.6227	4.25037	5868.55	4.25036	-0.00000
18.5000	34.6138	4.59440	6055.66	4.59440	0.00001
24.0000	34.6042	5.15055	6346.16	5.15056	0.00001
29.0000	34.5992	5.67075	6605.99	5.67074	-0.00001
32.5000	34.5965	6.04198	6785.15	6.04198	0.00000

f = Instrument Output(Hz) * sqrt(1.0 + WBOTC * t) / 1000.0

 $t = temperature \ (^{\circ}C); \quad p = pressure \ (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$

Conductivity (S/m) = (g + h * f^2 + i * f^3 + j * f^4) /10 (1 + δ * t + ϵ * p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

