## **SEA-BIRD ELECTRONICS, INC.**

1808 136th Place N.E., Bellevue, Washington, 98005 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0219 CALIBRATION DATE: 04-Aug-09

SBE 45 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 1.737743e - 005a1 = 2.736821e-004a2 = -2.328203e-006a3 = 1.493926e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	710472.5	1.0000	-0.0000
4.5000	606867.1	4.5000	0.0000
15.0000	385682.5	15.0000	-0.0000
18.5000	333660.9	18.5000	-0.0000
23.9999	267305.3	23.9999	0.0000
29.0000	219836.3	29.0000	-0.0000
32.5000	192354.5	32.5000	0.0000

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

0.63

