Conductivity Calibration Report

Customer:	Pacific Marine Envir	onmental Lab	
Job Number:	66476	Date of Repor	rt: 12/13/2011
Model Number:	SBE 37SM	Serial Numbe	er: 37SM28082-2336
sensor drift. If the	calibration identifies a pro rk is completed. The 'as red	as received', without cleaning or adjus blem or indicates cell cleaning is nece ceived' calibration is not performed if	essary, then a second calibration is
conductivity. Users sensor condition du corrections for drift	must choose whether the 'a ring deployment. In SEAS	led, listing the coefficients used to cons received' calibration or the previous OFT enter the chosen coefficients. Toult the SEASOFT manual). Calibrates.	s calibration better represents the The coefficient 'slope' allows small
'AS RECEIVED C	CALIBRATION'	✓ Perf	formed
Date: 12/13/2011		Drift since last cal:	-0.00040 PSU/month*
Comments:			
'CALIBRATION A	AFTER CLEANING &	REPLATINIZING' Perf	Formed V Not Performed
Date:]	Drift since Last cal:	PSU/month*
Comments:			
*Measured at 3.0	S/m		

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.