Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Pacific Marine E	nvironmental Lab		
Job Number:	86981	Date of Re	port:	11/25/2015
Model Number	SBE 39	Serial Num	ıber:	3928082-0806
If the calibration id calibration is not po	lentifies a problem, the erformed if the sensor	nted 'as received', without adjustments, on a second calibration is performed aftics damaged or non-functional, or by cu	er work is comp stomer request.	leted. The 'as received'
must choose wheth during deployment.	er the 'as received' cali In SEASOFT enter to ations (consult the SE	provided, listing coefficients to convert sibration or the previous calibration between the chosen coefficients. The coefficient ASOFT manual). Calibration coefficient	ter represents th 'offset' allows o	e sensor condition a small correction for
Date: 11/25/2015	5	Drift since last cal:	-0.00013	Degrees Celsius/year
Comments:				
'CALIBRATION	AFTER REPAIR'	□ P -	erformed	✓ Not Performed
Date:		Drift since Last cal:		Degrees Celsius/year
Comments:				