

Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	Date of	f Report	:	11/20/2015
Model Number	SBE 37SM	Serial	Number	: 3	7SM28082-2331
the calibration iden	tifies a problem, then	ated 'as received', without adjustn a second calibration is performed is damaged or non-functional, or	after work	is complete	ů ů
must choose whethe during deployment.	er the 'as received' cali In SEASOFT enter t ations (consult the SE	provided, listing coefficients to co bration or the previous calibrati he chosen coefficients. The coef ASOFT manual). Calibration co	on better re ficient 'offs	presents the et' allows a btained afte	e sensor condition a small correction for
115 KECEI VED C	ALIDIMATION		1 6110	inica	
Data: 11/20/2015		Duift aimes less	2011	<u>ተሀ ሀሀሀሀል</u>	Degrees Celsius/voor
Date: 11/20/2015	5	Drift since last	cal:	+0.00008	Degrees Celsius/year
Comments:	_	Drift since last			
	_	Drift since last	cal:		Degrees Celsius/year Not Performed
Comments:	_	Drift since last	Perfo		