Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Job Number:	86981	Date	of Repo	rt:	11/23/2015
Model Number	SBE 37SM	Seria	ıl Numb	er: 3	37SM28082-2333
the calibration iden	tifies a problem, then	nted 'as received', without adjus a second calibration is perform is damaged or non-functional,	ed after wo	rk is complet	0 0
An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data. 'AS RECEIVED CALIBRATION' Performed Not Performed					
		5 10. 1			
Date: 11/22/2015	וע	Drift since las	st cal:	-0.00013	Degrees Celsius/year
	_		<u> </u>		
Comments:	_				
Comments:	AFTER REPAIR'		□ Peri	formed	✓ Not Performed
	AFTER REPAIR'	Drift since La		formed	✓ Not Performed Degrees Celsius/year