## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 4078 CALIBRATION DATE: 22-Nov-15

SBE 37 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

## **COEFFICIENTS:**

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT	INSTRUMENT	RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (Hz)	COND (S/m)	(S/m)
22.0000	0.0000	0.0000	2641.51	0.0000	0.00000
1.0000	34.6838	2.96572	5183.39	2.96573	0.00002
4.5000	34.6647	3.27183	5377.23	3.27181	-0.00002
15.0000	34.6227	4.25037	5954.02	4.25036	-0.00001
18.5000	34.6138	4.59440	6143.71	4.59440	0.00000
24.0000	34.6042	5.15055	6438.27	5.15056	0.00001
29.0000	34.5992	5.67075	6701.78	5.67076	0.00001
32.5000	34.5965	6.04198	6883.50	6.04197	-0.00001

f = Instrument Output(Hz) \* sqrt(1.0 + WBOTC \* t) / 1000.0

 $t = temperature \ (^{\circ}C); \quad p = pressure \ (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$ 

Conductivity (S/m) = (g + h \*  $f^2$  + i \*  $f^3$  + j \*  $f^4$ ) /10 (1 +  $\delta$  \* t +  $\epsilon$  \* p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

