Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

		_			
Job Number:	77407	Date	of Report:		2/7/2014
Model Number	SBE 16Plus	Seria	l Number:	16	P63320-6826
If the calibration id	lentifies a problem, the	nted 'as received', without adjust en a second calibration is perfor is damaged or non-functional, o	ned after wor	k is complete	
must choose whethe during deployment.	er the 'as received' cal In SEASOFT enter t	provided, listing coefficients to consider the previous calibration or the previous calibration coefficients. The coefficients and coefficients are manual.	ion better rep fficient 'offse	resents the se t' allows a sn	ensor condition nall correction for
'AS RECEIVED C	CALIBRATION'		✓ Perform	med	Not Performed
'AS RECEIVED (Date: 2/7/2014	CALIBRATION'	Drift since las		med	Not Performed Degrees Celsius/year
	CALIBRATION'	Drift since las			
Date: 2/7/2014	CALIBRATION'	Drift since las			
Date: 2/7/2014		Drift since las		0.00005	Degrees Celsius/year
Date: 2/7/2014 Comments:		Drift since las	t cal: +	0.00005	Degrees Celsius/year