## **SEA-BIRD ELECTRONICS, INC.**

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 3762 CALIBRATION DATE: 20-Jan-11 SBE 37 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 3.136573e-005 a1 = 2.668724e-004 a2 = -1.568927e-006a3 = 1.372119e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	642024.4	1.0000	-0.0000
4.4999	550202.7	4.4999	0.0000
15.0000	352951.8	15.0000	0.0000
18.5000	306251.9	18.4999	-0.0001
24.0000	246450.9	24.0001	0.0001
29.0000	203484.2	29.0000	-0.0000
32.5001	178520.9	32.5001	-0.0000

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

