Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 1804 CALIBRATION DATE: 30-Sep-16 SBE 37 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT	INSTRUMENT	RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (Hz)	COND (S/m)	(S/m)
22.0000	0.0000	0.0000	2658.86	0.0000	0.00000
1.0000	34.8769	2.98065	5344.47	2.98066	0.00001
4.5000	34.8565	3.28814	5547.28	3.28815	0.00000
15.0000	34.8141	4.27137	6150.10	4.27135	-0.00002
18.5000	34.8053	4.61707	6348.12	4.61706	-0.00001
24.0000	34.7959	5.17593	6655.45	5.17595	0.00002
29.0000	34.7913	5.69868	6930.17	5.69870	0.00002
32.5000	34.7892	6.07180	7119.51	6.07178	-0.00002

f = Instrument Output(Hz) * sqrt(1.0 + WBOTC * t) / 1000.0

 $t = temperature \ (^{\circ}C); \quad p = pressure \ (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$

Conductivity (S/m) = (g + h * f^2 + i * f^3 + j * f^4) /10 (1 + δ * t + ϵ * p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

