Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	Date of Rep	ort:	11/23/2015
Model Number	SBE 16Plus	Serial Numl	ber:	16P73164-7297
the calibration iden calibration is not pe	tifies a problem, then or erformed if the sensor	ated 'as received', without adjustments, a a second calibration is performed after w is damaged or non-functional, or by cust	ork is complet tomer request.	ed. The 'as received'
must choose whethe during deployment.	er the 'as received' cali In SEASOFT enter to ations (consult the SE	provided, listing coefficients to convert selibration or the previous calibration bette the chosen coefficients. The coefficient 'ASOFT manual'). Calibration coefficien	er represents the foffset' allows a	e sensor condition a small correction for
Date: 11/21/2015		Drift since last cal:	-0.00039	
Comments:	_			
'CALIBRATION AFTER REPAIR'		□ Pe	rformed	✓ Not Performed
Date:]	Drift since Last cal:		Degrees Celsius/year
Comments:				