Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2331 CALIBRATION DATE: 20-Nov-15

SBE 37 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT	INSTRUMENT	RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (Hz)	COND (S/m)	(S/m)
22.0000	0.0000	0.00000	2658.53	0.00000	0.00000
1.0000	34.6081	2.95986	5354.26	2.95986	-0.00000
4.5000	34.5879	3.26529	5557.78	3.26529	0.00000
15.0000	34.5450	4.24184	6162.62	4.24183	-0.00000
18.5000	34.5360	4.58518	6361.30	4.58519	0.00001
24.0000	34.5264	5.14025	6669.63	5.14025	0.00000
29.0000	34.5214	5.65943	6945.27	5.65942	-0.00001
32,5000	34.5189	6.02997	7135.27	6.02997	0.00001

f = Instrument Output(Hz) * sqrt(1.0 + WBOTC * t) / 1000.0

 $t = temperature \ (^{\circ}C); \quad p = pressure \ (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$

Conductivity (S/m) = (g + h * f^2 + i * f^3 + j * f^4) /10 (1 + δ * t + ϵ * p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

