## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 4139 CALIBRATION DATE: 29-Jun-12

SBE16plus TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 1.290210e-003a1 = 2.504298e - 004a2 = 1.235779e-006a3 = 1.019135e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT(n)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	632655.600	0.9999	-0.0001
4.5000	562041.100	4.5001	0.0001
15.0000	386440.455	14.9998	-0.0002
18.5000	339209.300	18.5002	0.0002
24.0000	275059.200	23.9999	-0.0001
29.0000	226202.000	29.0001	0.0001
32.5000	196689.182	32.4999	-0.0001

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e+009 + 1.024e+008) / (2.048e+004 - MV \* 2.0e+005)

Temperature ITS-90 =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

