## **Conductivity Calibration Report**

Customer:	Pacific Marine Environmental Lab					
Job Number:	77407	Date	Date of Report:		2/7/2014	
Model Number	SBE 16Plus	Seria	l Number:	16P6870	)1-6902	
sensor drift. If the	calibration identifies a rk is completed. The '	ated 'as received', without cleani or problem or indicates cell clean as received' calibration is not pe	ing is necessary	, then a second co	alibration is	
An 'as received' calibration certificate is provided, listing the coefficients used to convert sensor frequency to conductivity. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients. The coefficient 'slope' allows small corrections for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair or cleaning apply only to subsequent data.						
'AS RECEIVED CALIBRATION'				Performed		
Date: 2/7/2014		Drift since las	t cal:	-0.00030	PSU/month	
Comments:						
'CALIBRATION AFTER CLEANING & REPLATINIZING' ☐ Performed ✓ Not Performed						
Date:		Drift since La	st cal:		PSU/month	
Comments:						
*Measured at 3.0	S/m					

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.