Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 0041 CALIBRATION DATE: 28-Apr-19

SBE 49 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

a0 = 8.669274e-004 a1 = 2.760271e-004 a2 = -1.484860e-006 a3 = 1.918920e-007

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (counts)	(° C)	(° C)
1.0000	682091.153	1.0001	0.0001
4.5000	601809.119	4.4998	-0.0002
15.0000	399696.983	15.0001	0.0001
18.5000	344653.356	18.5002	0.0002
23.9999	269331.000	23.9997	-0.0002
29.0000	211478.814	28.9999	-0.0001
32.5001	176299.780	32.5002	0.0001

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV * 2.295e + 0.10 + 9.216e + 0.08) / (6.144e + 0.04 - MV * 5.3e + 0.05)

Temperature ITS-90 (°C) = $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

