**Customer:** 

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

## Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	Da	te of Repo	rt:	11/23/2015
Model Number	SBE 37SM	Ser	rial Numb	er: 3	37SM25541-1852
the calibration iden	tifies a problem, then	nted 'as received', without adj a second calibration is perfor is damaged or non-functiona	med after wo	ork is complet	0 0
must choose whethe during deployment.	er the 'as received' cali In SEASOFT enter t ations (consult the SE	provided, listing coefficients to ibration or the previous calib he chosen coefficients. The o ASOFT manual). Calibration	ration better coefficient 'o n coefficients	represents th ffset' allows (	ne sensor condition a small correction for
AS RECEIVED C	_			-0.00038	
Date: 11/21/2015	5	Drift since l	last cal:	-0.00030	Degrees Celsius/year
Date: 11/21/2015 Comments:	5]	Drift since l	last cal:	-0.00030	Degrees Celsius/year
		Drift since l	_	formed	Degrees Celsius/year  ✓ Not Performed
Comments:		Drift since l	□ Peri		