Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2786 CALIBRATION DATE: 10-Feb-17

SBE 3 TEMPERATURE CALIBRATION DATA

0.00000

0.00002

ITS-90 TEMPERATURE SCALE

29.0000

32.5000

COEFFICIENTS:

g = 4.37639263e-003 h = 6.44299888e-004 i = 2.29169278e-005 j = 2.13033208e-006 f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3061.409	-1.4999	0.00005
1.0000	3237.524	1.0000	-0.00003
4.5000	3496.235	4.4999	-0.00008
8.0000	3769.484	8.0000	-0.00002
11.5000	4057.657	11.5001	0.00007
15.0000	4361.126	15.0001	0.00013
18.5000	4680.239	18.4999	-0.00005
22.0000	5015.385	21.9999	-0.00009
25.5000	5366.905	25.5000	-0.00000

f = Instrument Output (Hz)

29.0000

32.5000

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

5735.108

6120.319

Residual (°C) = instrument temperature - bath temperature

