Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Pacific Marine E	nvironmental Lab		
Job Number:	77407	Date of Re	eport:	2/11/2014
Model Number	SBE 39	Serial Nun	nber:	3925374-0580
If the calibration id calibration is not po	lentifies a problem, the erformed if the sensor	ated 'as received', without adjustments, on a second calibration is performed aft is damaged or non-functional, or by cu provided, listing coefficients to convert	ter work is comp ustomer request.	pleted. The 'as received'
must choose wheth during deployment.	er the 'as received' cali In SEASOFT enter to ations (consult the SE	ibration or the previous calibration bet he chosen coefficients. The coefficien ASOFT manual). Calibration coefficie	tter represents ti t 'offset' allows	he sensor condition a small correction for
Date: 2/11/2014]	Drift since last cal:	-0.00002	Degrees Celsius/year
Comments:				
'CALIBRATION	AFTER REPAIR'	□ F	Performed	✓ Not Performed
Date:		Drift since Last cal:	:	Degrees Celsius/year
Comments:				