Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	86981	Date of Repor	12/8/2015
Model Number	SBE 37SM	Serial Numbe	r: 37SM25429-1805
the calibration iden	tifies a problem, then	ated 'as received', without adjustments, allo a second calibration is performed after wor is damaged or non-functional, or by custon	rk is completed. The 'as received'
must choose whethe during deployment. drift between calibra subsequent data.	er the 'as received' cal. In SEASOFT enter t ations (consult the SE	provided, listing coefficients to convert sens libration or the previous calibration better r the chosen coefficients. The coefficient 'of ASOFT manual). Calibration coefficients	represents the sensor condition fset' allows a small correction for obtained after a repair apply only to
AS RECEIVED CALIBRATION'		✓ Perf	ormed Not Performed
Date: 11/21/2015	5]	Drift since last cal:	-0.00032 Degrees Celsius/year
Comments:			
CALIBRATION A	AFTER REPAIR'	✓ Perfo	ormed
Date: 12/8/2015]	Drift since Last Cal:	N/A Degrees Celsius/year
Comments: The temperature p			