

SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

Service Request Date

Sales Order

1005502670 25-SEP-2017

314766125

CUSTOMER INFORMATION

Name: NOAA PMEL - PACIFIC MARINE ENVIRO LAB

Account: 40279844 DAVID STRAUSZ

DAVID.STRAUSZ@NOAA.GOV

206-526-4510

Bill To Address

7600 SAND POINT WAY NE;

SEATTLE,WA,98115-6349,US

PO Number: WARRANTY

Ship To Address

SUPPLY CENTER / RECEIVING;7600 SAND POINT WAY NE,

BLDG 8;

SEATTLE, WA, 98115, US

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM24425-2355

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Problems Found:

Battrey pylon has stripped screw hole.

Services Performed:

Performed initial diagnostic evaluation.

Replaced battery pylon.

Performed "POST" cruise calibration.

Performed pressure calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed complete system check and full diagnostic evaluation.

Item	Item Description	Qty

Unbilled Items

Item	Item Description	Qty
80982	SBE37SM uCAT BATTERY PYLON ASSY INT PWR 3 PIN	1
SERVICE37	COMPLETE EXTERNAL INSPECTION. TEST ALL FUNCTIONS. CALIBRATE C & T, C&P AND RECAL IF NECESSARY. REPLACE END CAP O-RINGS A (FRRF)	1



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

SERVICE REPORT

Phone Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com

Service Request Date Sales Order

25-SEP-2017 314766125

1005502670