

Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Job Number:	77407	Date of Rep	ort:	2/5/2014
Model Number	SBE 37SM	Serial Numb	ber:	37SM26834-2023
the calibration iden	tifies a problem, then d	ated 'as received', without adjustments, a a second calibration is performed after w is damaged or non-functional, or by cust	vork is comple	eted. The 'as received'
must choose whethe during deployment.	er the 'as received' cali In SEASOFT enter to ations (consult the SE	provided, listing coefficients to convert se ibration or the previous calibration bette he chosen coefficients. The coefficient 'ASOFT manual). Calibration coefficien	er represents t 'offset' allows	he sensor condition a small correction for
Date: 2/5/2014	7	Drift since last cal:	-0.00014	
Comments:	_	'		
'CALIBRATION A Date: Comments:	AFTER REPAIR'	☐ Pe Drift since Last cal:	rformed	✓ Not Performed Degrees Celsius/year