Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Pacific Marine En	vironmental Lab		
Job Number:	86981	Date of Rep	ort:	12/2/2015
Model Number	SBE 39	Serial Num	ber:	3936948-1640
the calibration iden calibration is not p	ntifies a problem, then a erformed if the sensor is	ed 'as received', without adjustments, a second calibration is performed after v damaged or non-functional, or by cus	work is comple ctomer request	eted. The 'as received'
must choose wheth during deployment	er the 'as received' calib . In SEASOFT enter the ations (consult the SEA	rovided, listing coefficients to convert so ration or the previous calibration bette chosen coefficients. The coefficient SOFT manual). Calibration coefficien	er represents t 'offset' allows	he sensor condition a small correction for
Date: 12/2/2015		Drift since last cal:	+0.0001	
Comments:	_			<u> </u>
'CALIBRATION	AFTER REPAIR'	□ Pe	erformed	✓ Not Performed
Date:		Drift since Last cal:		Degrees Celsius/year
Comments:				