Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Pacific Marine E	nvironmental Lab		
Job Number:	86981	Date of Repo	ort:	11/23/2015
Model Number	SBE 37SM	Serial Numb	oer:	37SM36048-3766
the calibration iden calibration is not p	ntifies a problem, then a erformed if the sensor i	ted 'as received', without adjustments, al a second calibration is performed after w is damaged or non-functional, or by cust	ork is comple comer request	eted. The 'as received'
must choose wheth during deployment drift between calibr subsequent data.	er the 'as received' calid In SEASOFT enter the ations (consult the SEA	rovided, listing coefficients to convert serbration or the previous calibration better the chosen coefficients. The coefficient of ASOFT manual). Calibration coefficient	r represents t offset' allows ts obtained aj	he sensor condition a small correction for fter a repair apply only to
'AS RECEIVED (=	<u>✓</u> Per	rformed	Not Performed
Date: 11/21/2015	5	Drift since last cal:	+0.0000	1 Degrees Celsius/year
Comments:				
'CALIBRATION	AFTER REPAIR'	□ Pei	rformed	✓ Not Performed
	AFTER REPAIR'		rformed	
CALIBRATION Date:	AFTER REPAIR'	☐ Per	rformed	✓ Not Performed Degrees Celsius/year