

Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 5584 CALIBRATION DATE: 24-Aug-23 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.32395887e-003 h = 6.37970034e-004 i = 2.18344333e-005 j = 2.01255421e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	2832.127	-1.4999	0.00007
1.0000	2995.594	0.9999	-0.00010
4.5000	3235.789	4.5000	-0.00003
8.0000	3489.531	8.0000	0.00003
11.5000	3757.183	11.5000	0.00002
15.0000	4039.112	15.0001	0.00005
18.5000	4335.655	18.5000	0.00000
22.0000	4647.155	22.0000	-0.00004
25.5000	4973.943	25.5000	-0.00001
29.0000	5316.322	29.0000	-0.00003
32.5000	5674.603	32.5000	0.00003

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0 / f)] + i[ln^2(f0 / f)] + j[ln^3(f0 / f)]\} - 273.15$

Residual (°C) = instrument temperature - bath temperature

