Conductivity Calibration Report

Customer:	Pacific Marine Environmental Lab				
Job Number:	83585	Date of Report: 3/4/20		2015	
Model Number	SBE 37SM	Serial N	Number:	37SM26834-2025	
sensor drift. If the	calibration identifies a rk is completed. The '	ated 'as received', without cleaning problem or indicates cell cleaning as received' calibration is not perfo	g is necessar	y, then a second o	calibration is
An 'as received' calibration certificate is provided, listing the coefficients used to convert sensor frequency to conductivity. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients. The coefficient 'slope' allows small corrections for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair or cleaning apply only to subsequent data.					
'AS RECEIVED CALIBRATION' ✓ Performed Not Performed					
Date: 3/4/2015]	Drift since last o	al:	-0.00030	PSU/month
Comments:	_				_
'CALIBRATION AFTER CLEANING & REPLATINIZING' ☐ Performed ✓ Not Performed					
Date:		Drift since Last	cal:		PSU/month
Comments:					
*Measured at 3.0	S/m				

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.