

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request Date

PO Number:

Sales Order

Phone

1005518695 29-SEP-2023

+1-425-643-9866

320697646

SERVICE REPORT

CUSTOMER INFORMATION

Name: NOAA - PMEL PACIFIC MARINE ENVIRO LAB

Account: 40279844 DAVID STRAUSZ

DAVID.STRAUSZ@NOAA.GOV

206-526-4510

Bill To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB

7600 SAND POINT WAY NE

SEATTLE,WA,98115-6349,US

Ship To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB SUPPLY CENTER / RECEIVING 7600 SAND POINT WAY NE, BLDG 8

SEATTLE,WA,98115,US

PRODUCT INFORMATION

Item: 03F.LEGACY

Item Description: (LEGACY) SBE 03F Temperature Sensor

Serial: 030696

Special Notes

Services Requested:

CAL_3

Problems Found:

The temperature was found to have excessive drift.

The end cap seized to the housing.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced the housing, endpcap, and temperature probe.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
REP3PROB	Replace SBE 3 thermistor probe	1

Unbilled Items

Item	Item Description	Qty
80004	FAST TEMP 70 MS THERMISTOR PROBE ASSEMBLY	1
30806	L-SEAL, LS021	1
23021C	THERM. HOUSING, 6800M, HARDCOATED	1
231004	BACKUP RING FOR LS021 L-SEAL /DWG 21017B	1



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

WV

Phone

+1-425-643-9866 www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

SERVICE REPORT

Service Request Date Sales Order **1005518695** 29-SEP-2023

320697646

233235	THREADED BRASS RING, .25" THICK	1
23011C	THERMOMETER ENDCAP, 6061 HARDCOATED	1



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request Date

Sales Order

Phone

1005518695 29-SEP-2023 320697646

+1-425-643-9866

SERVICE REPORT

PRODUCT INFORMATION

Item: 03P.LEGACY

Item Description: (LEGACY) SBE 03Plus Temperature Sensor

Serial: 03P5584

Special Notes
Services Requested:

CAL_3

Problems Found:

The temperature probe was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the temprature probe.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
REP3PROB	Replace SBE 3 thermistor probe	1

Unbilled Items

Item	Item Description	Qty
80004	FAST TEMP 70 MS THERMISTOR PROBE ASSEMBLY	1
30806	L-SEAL, LS021	1
231004	BACKUP RING FOR LS021 L-SEAL /DWG 21017B	1