Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 3765 CALIBRATION DATE: 18-Oct-16 SBE 37 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.025194e+000	CPcor = -9.5700e-008
h = 1.406151e-001	CTcor = 3.2500e-006
i = -8.014872e - 006	WBOTC = $-8.7050e-006$
j = 2.212962e-005	

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT	INSTRUMENT	RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (Hz)	COND (S/m)	(S/m)
22.0000	0.0000	0.0000	2699.06	0.00000	0.00000
1.0000	34.5922	2.95863	5311.78	2.95863	0.00000
4.5000	34.5730	3.26402	5510.82	3.26401	-0.00001
15.0000	34.5315	4.24036	6103.09	4.24038	0.00002
18.5000	34.5229	4.58363	6297.85	4.58363	0.00000
24.0000	34.5137	5.13856	6600.30	5.13855	-0.00002
29.0000	34.5080	5.65748	6870.82	5.65747	-0.00001
32.5000	34.5060	6.02797	7057.47	6.02798	0.00001

f = Instrument Output(Hz) * sqrt(1.0 + WBOTC * t) / 1000.0

 $t = temperature \ (^{\circ}C); \quad p = pressure \ (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$

Conductivity (S/m) = (g + h * f^2 + i * f^3 + j * f^4) /10 (1 + δ * t + ϵ * p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

