Customer:

Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Job Number:	86981	Date of Re	port:	11/20/2015
Model Number	SBE 37SM	Serial Num	iber:	37SM26834-2026
the calibration iden	tifies a problem, then	ated 'as received', without adjustments, a second calibration is performed after is damaged or non-functional, or by cu	work is comple	ted. The 'as received'
must choose whethe during deployment.	er the 'as received' call In SEASOFT enter t ations (consult the SE	provided, listing coefficients to convert sibration or the previous calibration bethe chosen coefficients. The coefficient ASOFT manual). Calibration coefficients	ter represents the 'offset' allows	ne sensor condition a small correction for
Date: 11/20/2015		Drift since last cal:	-0.00005	
Comments:	_			
	A EVEED DEDAYE!		c 1	
'CALIBRATION A	AFTER REPAIR'	□ P	erformed	✓ Not Performed
'CALIBRATION A	AFTER REPAIR'	☐ P Drift since Last cal:	erformed	✓ Not Performed Degrees Celsius/year
<u> </u>	AFTER REPAIR'		erformed	