PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

Chlorophyll WETStar Characterization

Date: January 4, 2013 S/N: WS3S-848P

Chlorophyll concentration expressed in µg/l can be derived using the equation:

 $CHL(\mu g/I) = Scale Factor x (Output - Clean Water Offset)$

Analog output

Clean Water Offset (CWO) 0.078 VScale Factor (SF) 15.1 µg/l/V

Maximum Output5.49 VResolution0.21 mVAmbient Characterization Temperature $22 \pm 1\%$

Current Draw 30 mA @ 12V (typical)

12-hour Stability 0.19 mV/hr Temperature Stability, 25–2 $^{\circ}$ 0.38 mV/ $^{\circ}$

Range	
15 μg/l	0
81 µg/l	Χ
150 µg/l	0

Definitions:

CWO: Clean Water Offset value obtained using pure filtered de-ionized water.

SF: Scale Factor is used to convert the fluorescence response of the instrument into chlorophyll-a concentration. Scale Factor is determined at WET Labs during a cross calibration using a liquid fluorescent standard and a reference fluorometer whose chlorophyll fluorescence response has been characterized in a laboratory using a mono-species lab culture of *Thalassiosira weissflogii* phytoplankton.

Maximum Output: Maximum signal output of the fluorometer.

Resolution: Standard deviation of 1 minute of clean water data, sampled once per second. **Ambient Characterization Temperature:** Room temperature at time of characterization.

Current Draw: The amount of current the instrument uses for operation.

12-hour Stability: Deviation of output averaged over 12 hours.

Temperature Stability: Measured output variation per degree.

WS3S-848P.xls Revision I 10/3/07

PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

WETStar Calibration and Repairs

Date January 4, 2013 Customer NOAA

S/N# WS3S-848P Repair Order 16178

Standard Service

• Performed noise test: 1 sample/sec for 60 sec

• Performed stability test: 1 sample/min for 12 hrs

• Performed temperature test: 25–2 ℃

• Performed saturation test

Shake-tested unit

• Pressure-tested unit

• Updated unit's calibration sheet

Additional Repairs

Parts Replaced: O-Rings

Comments

WETStar was re-calibrated with 25ppb Uranine.

WS3S-848P.xls Revision I 4/17/08