Records for Mooring: 19BS-5A

alternate name:

<u>Deployment</u> <u>Recovery</u>

Cruise Number: **DY1908** Cruise Number:

Deployment Date/Time (GMT): Recovery Date/Time (GMT):

2019-09-22 23:50:00

GPS latitude: **59 54.910 N** GPS latitude:

GPS longitude: 171 42.070 W GPS longitude:

CTD cast no: CTD008 CTD cast no:

Actual Deployment Depth (m): **69.7**

Timekeeper: Bridge Timekeeper:

Chief Scientist: Proctor Chief Scientist:

Pre-Deployment - Mooring Diagram

Estimated latitude (N): 59 54.6 N

Estimated longitude (W): 171 42.0 W

Estimated Deployment depth: 71

Estimated Recovery Date: 2020-09-15

1 of 3 9/29/19, 5:47 PM

Records for Mooring: 19BS-5A

Comments:

Check Depth before Deployment All ecos, sbe37 and sbe39 are lithium eco sample rate setup wrong (1min), discovered while deploying. swap w/4B instrument. Started at :30 min EDD Fabric Test: (S. Anderson for contact) Tube 3 @ 18m Tube 4 @ 68m

Deployed Instruments: 19BS-5A

11	Actual Depth	Instrument	Serial No.	Instrument notes	Performance Notes	Prepped	Dep.	Rec.	Da Sta	
15	0	ADCP float					y			
15	0	<u>OSP-2300</u>	<u>70295</u>	On Seacat		У	y			
15	0	SBE-16	1815	pump SN-056537		У	У			
16	0	30" Steel Float					У			
17	0	SBE-37	1850			У	y			
18	0	Eco- Fluorometer FLSB	<u>1795</u>	on at 23:30		У	У			
20	0	<u>SBE-39</u>	<u>1623</u>	w/P		У	y			
23	0	SBE-39	<u>5473</u>			У	y			
25	0	<u>QSP-2300</u>	<u>70545</u>	On Seacat		У	y			
25	0	SBE-16	7297	pump SN-053210		У	У			
27	0	SBE-39	0992	w/P		У	y			
28	0	40" Steel Float					У			
32	0	SBE-37	<u>1860</u>			У	y			

2 of 3 9/29/19, 5:47 PM

35	0	SBE-39	<u>1805</u>	w/P	У	У		
40	- θ	- <u>SBE-39</u>	- <u>5473</u>	error in mooring document setup remove instrument		-n		
40	0	<u>QSP-2300</u>	70368	On Seacat	У	У		
40	0	SBE-16	4287	pump SN-056537	У	У		
45	0	<u>SBE-39</u>	<u>3775</u>	w/P	У	У		
50	0	SBE-39	<u>0564</u>		У	y		
55	0	SBE-37	<u>1851</u>		У	y		
60	0	SBE-39	<u>1624</u>	w/P	У	У		
65	0	RCMSG	1734	30 min intervals, start 20 Sept 2019, alk batts	У	У		
65	0	<u>Optode</u>	<u>2190</u>	Mod 4330	y	У		
67	0	SBE-39	<u>0566</u>		У	y		
69	0	8242AA Release	33953		У	У		

Does the release have new batteries?: • Yes No If not new, how many months were batteries used? 0 months

Bell

PMEL EcoFOCI

3 of 3