

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

Customer:	Pacific Marine Er	nvironmental Lab		
Job Number:	83585	Date of Rep	ort:	3/4/2015
Model Number	SBE 37SM	Serial Num	ber:	37SM40084-3979
If the calibration is calibration is not possible. An 'as received' calibration is not possible.	lentifies a problem, thei erformed if the sensor i libration certificate is p	ted 'as received', without adjustments, a n a second calibration is performed afte is damaged or non-functional, or by cus rovided, listing coefficients to convert se bration or the previous calibration bette	r work is comp tomer request. ensor frequency	leted. The 'as received' y to temperature. Users
during deployment	In SEASOFT enter the attions (consult the SEA	ne chosen coefficients. The coefficient ASOFT manual). Calibration coefficien	'offset' allows o	a small correction for
Date: 3/4/2015	7	Drift since last cal:	-0.00014	
Comments:	_			
'CALIBRATION Date:	AFTER REPAIR'	☐ Pe	erformed	✓ Not Performed Degrees Celsius/year
Comments:				