Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2341 CALIBRATION DATE: 04-Feb-14

SBE 37 PRESSURE CALIBRATION DATA 1450 psia S/N 1230

COEFFICIENTS:


PA0 =	-1.151328e-001	PTCA0 :	=	-2.156386e+002
PA1 =	6.868715e-002	PTCA1 :	=	-8.379614e-002
PA2 =	-4.905690e-009	PTCA2 =	=	3.612934e-004
		PTCB0 :	=	2.474413e+001
		PTCB1 :	=	-5.750000e-004

PTCB2 = 0.000000e+000

PRESSURE S PRESSURE PSIA	PAN CALIB INST OUTPUT	_	N COMPUTED PRESSURE	ERROR %FS	THERM TEMP ITS90	AL CORRE INST OUTPUT	CCTION TEMP ITS90	SPAN MV
14.75	-0.9	22.1	14.76	0.00	32.50	9.95	-5.00	24.75
588.35	8352.0	22.0	588.43	0.01	29.00	10.32	35.00	24.72
875.45	12535.6	22.0	875.50	0.00	24.00	10.80		
1162.45	16720.0	22.0	1162.45	-0.00	18.50	11.11		
1449.38	20906.6	22.0	1449.38	0.00	15.00	10.91		
1162.39	16719.1	22.0	1162.38	-0.00	4.50	11.99		
875.35	12532.9	21.9	875.31	-0.00	1.00	12.38		
588.49	8351.9	21.9	588.42	-0.00				
301.55	4173.5	21.9	301.54	-0.00				
14.76	-0.9	22.1	14.76	0.00				

x = pressure output - PTCA0 - PTCA1 * t - PTCA2 * t^2 n = x * PTCB0 / (PTCB0 + PTCB1 * t + PTCB2 * t^2) pressure (psia) = PA0 + PA1 * n + PA2 * n^2

Date, Avg Delta P %FS



• 04-Feb-14 0.00